COSMETICS – O.E.M. COLORS & MATERIALS	¢ 400 00
Refinish/Paint (All visible surfaces & pedestal stand)	\$ 400.00
Repainting & touch-up (a-la-carte)	\$ 65.00 per major panel/item \$ 35.00 per minor panel/item
Armrest recovered (BLACK VINYL)	
Replacement armrest end caps (molded polyurethane in RED or BLACK)	\$ 59.00 per pair
Replacement Head Cover	\$195.00 per pail \$195.00 limited availability
періасеннені пеац сочет	\$195.00 illilited availability
FUNCTIONAL REBUILDS & REPLACEMENTS	
Full Transport Clean / Paint	\$275.00
The entire deck is stripped down and given a bath. Functional parts and hardware a as necessary. Includes re-painting of the deck surround.	re replaced and/or lubricated & adjusted
Capstan Motor Rebuild	\$350.00
Reel Motors Rebuild	\$280.00 ea. x2 for "The Works" (\$560.00)
Reel motor Turntables	\$ 65.00 ea. x2 for "The Works" (\$130.00)
Covered with new neoprene/cork composite & machined flat.	
$\textbf{Mag-Reels} - \text{ Precision } \text{ NAB adapters machined from solid billet aluminum.} \\ \dots \\ \dots$.\$329.00/pair
Auto reel centering offering low wow & flutter and a great look!	
Rebuild Rotary Solenoids & Tension arm Assemblies	\$165.00 ea. x2 for "The Works" (\$330.00)
non-rebuildable version - converted to new version	add \$100.00 ea.
Capstan w/Optical Encoder Assembly incl. trade-in of core	\$365.00 (no trade price - \$505.00)
Timing Idler Assembly incl. trade-in of core	\$275.00 (no trade price - \$375.00)
Above items covered with our proprietary, "RED" high performance elastomer, precision ground	& slit. Always tested for speed & flutter performanc
Quartz/Pyrex Tape Lifter Sleeves (2)	set of (2) limited availability
Bearings for rebuildable tape guides	ea. (bearing prices subject to change)
Head assembly - ultrasonic clean, adjust & lubricate)
Rebuild 1/4" Tape guide incl. bearings & shims	ea. old non-rebuildable style must be replaced.
Rebuild 1/2" Tape guide incl. bearings & shims	ea. old non-rebuildable style must be replaced.
Replacement 1/4" Tape Guide (2 per machine)\$130.00	ea.
Replacement 1/2" Tape Guide (2 per machine)\$160.00	ea.
Note: A 1/4" machine converted to 1/2" will require replacement guide shafts, in ad	dition to dual bearings.
Rebuild OEM Scrape Flutter Filter for head assembly \$110.00	
Low-Noise TEF Scrape Flutter Filter Set (2) for head assembly\$375.00	
Remote Control w/25 ft extension	
Single point Search-to-Cue w/25 ft extension	
Accessory tray - original Ampex part	
Head relapping & replacement / track format conversion \$ by quo	
	tation, miles added to total
ELECTRONICS & "THE WORKS"	#20F 00
Test & wash all audio & control electronics	\$325.00
Cards are washed to a sparkle and all edge & harness connectors are cleaned and t	
Rebuild the Power Supply	\$450.00
Includes new electrolytic capacitors & rectifiers throughout with safely increased cap	acitance & current handling capacity.
Some required parts may be additional if there are problem components.	Φ000 00 (ΦΕ00 00)
Rebuild the Capstan Servo & Reel Control electronics	\$290.00 ea. (\$580.00)
Proper functioning of these cards is critical. The discreet PWM reel driver circuit is e	
create serious problems. We render a number of modifications which dramatically st	
Audio & other electronics repaired / restored to OEM specs - additional charges appl	•
This work is performed a-la-carte and will be added to your total. Most machines will require wo	
Xiron™ transformerless I/O modules	\$425.00 ea. w/ trade-in of your OEM I/O's
"The Works" includes all items marked with " • " \$4,175	5.00
This is the starting price point for a major rebuild. Includes a one year warranty	
	out of the and enterprise. A
assemblies & four months on rebuilt electronics. Price includes a 5% overall disc minimum \$3,000.00 deposit is required.	

prices subject to change without notice.

